

ENGINE MODEL: O-470-U (5)
ENGINE S/N: 469962
REG. NO: 97077
WORK ORDER: 339-09-2000

Printed by EBis (<http://www.datcomedia.com>)

DatcoMedia

1407 Marilyn Way
Santa Maria, CA 93454
Repair Station No. W1P23RTS

DATE: / /
TTE:
TSMOH: 709.9
TACH: 3269.9

Engine Entries

(9) R/R all six cylinders with overhauled O470U cylinder/valve assemblies with serviceable pistons and new rings gaskets & rocker shafts, from ONE STOP Aviation, Inc. CRS# XP3R981L w/o# 13212. Performed cylinder ground runs and flight test in accordance with TCM SB M89-7R1..... (62) C/W TCM AD 99-19-01 (crankshaft cheek cracks) and found to be N/A per engine s/n installed. No further action necessary..... (63) C/W TCM AD 00-08-51 (crankshaft material) and found to be N/A per engine s/n installed. No further action necessary..... (67) Cleaned all cylinder fuel primer nozzles....

Please mark the discrepancies you would like completed at this time with an X, then sign and return this form by faxing it to: 805-739-0902

I, as the owner or authorized representative thereof, hereby authorize the above repair work along with the necessary materials, and hereby grant Aero West Specialties, LLC and its employees permission to run engines, taxi aircraft, operate aircraft and test fly the aircraft herein described for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on this aircraft to secure the amount of repair thereto. Aero-West Specialties, LLC is not responsible for loss or damage to the aircraft or articles left in aircraft in the case of fire, theft and/or any other cause beyond Aero-West Specialties, LLC control. I further agree to pay any costs associated with any collection actions necessary for these charges. I understand that any warranties either expressed or implied, including any implied warranties of the merchantability or fitness for a particular purpose and neither assume, or authorize any other person to assume for the company any liability in connection with the sale of this part(s) and/or service. Buyer shall not be entitled to recover from the company any consequential damages to property damages for loss of use, loss of time, loss of profits and/or income, or any other incidental damages. Inside storage fee of \$20.00 a day is also due if aircraft is not picked up within 2 days after completion. Customer has removed all personal or removable items from the aircraft before delivery to Aero-West Specialties, LLC and Aero-West Specialties, LLC assumes no responsibility for anything left in the aircraft.

Note: A 5 % insurance charge will be added to all customer supplied parts.

By signing this agreement, you authorize Aero-West Specialties, LLC to purchase any parts necessary to complete the items you have chosen. A 50% deposit is required to start serving your airplane. You may send a check or use a credit card. You can fill out your MasterCard or Visa (only) information below. Estimate costs can vary up to ten percent without receiving a call from Aero-West Specialties, LLC.

Customer Release: I hereby authorize the following repair work to be done along with the necessary employees permission to operate and fly the aircraft herein described above. A mechanic's lien is hereby acknowledged on this aircraft to secure the amount this work order and any necessary cost for AWS to hire a collection agency and/or an attorney to collect any outstanding balance and all costs plus a reasonable attorney's fees and/or collection agency fee.

DATE: _____ SIGNED: _____ WORK ORDER: 339-09-2000

Certified Repair Station No. W1P23RTS